

# ACCIDENT REPORT

## LIPTON, RJUKAN

### February 22. 2015



#### Head of safety commission NKF.

**Odd Magne Øgreid** sikkerhet@klatring.no

On February 22, 2015, a 33-year old Italian climber lost his life in an accident while ice climbing at Rjukan.

Sunday morning, two male Italian climbers started to climb the route Lipton, graded WI7. They were part of a group of four Italian climbers visiting Rjukan. The route is located in the innermost part of the Upper Gorge; approximately 50 meters left of Rjukanfossen. One can easily see Lipton from the road (Rv 37). In the "Heavy water" guidebook, the description of the climb reads:

*"4 pitches. At the very end of the gorge, inside a huge groove, you will find this world classic. Start inside the groove (sometimes mixed) and climb as high as you can on thin ice to a belay under a roof. Traverse out right and gain the pillar (bring a Friend 2 for protection in the roof) and do some acrobatic moves to get established on the ice. Continue to the next roof for a belay. Continue through this roof to the top. Lipton should be considered as a serious climb and aspiring climbers should consider conditions carefully. The first pillar usually falls down at least twice each winter."*

The team decided to start early in order to take advantage of lower temperatures in the morning. The temperature was then about -4 degrees Celsius. The two climbers had known each other for about four years, and climbed several times together during this time. The assumed stronger climber of the two, which was also training to become a mountain guide, was to lead the first pitch. They used half ropes and the climber used standard procedure, placing

ice screws and clipping the ropes along the way. The accident happened while the climber was on the first pitch. After 30 vertical meters, the climber starts the crux traverse. The climber had traversed about 10 meters, and had obviously tackled the most challenging part when the accident happened.

The accident was triggered by massive amounts of ice (see photos on next page) that came loose and somehow pulled the climber along. It is not known whether an ice screw was attached to the falling ice, or whether the ice screw came loose as the ice collapsed. It is assumed that the last piece of protection placed, was an ice screw in the large hanging icicle on the traverse. The belayer reports that the climber was hit by falling ice, and since his protection for the traverse was now gone, he also experienced a large pendulum, and probably hit the rock face as well when the rope swung. The exact details of what happened during the fall is not known. The fall was arrested by an ice screw that held (see photo). When the rope came to rest, the climber had sustained massive injuries during the fall. He fell approximately 10 meters, and hung in free air after the fall. The belayer was sheltered and was not hit by the falling ice. Thus, it was possible to lower the climber directly to the ground.

The belayer moved the climber a short distance away, being afraid that more ice might fall down.

At the same time as the accident happened, four other climbers were scouting the conditions in the gorge from the road. They heard a loud crash of ice, and saw that the large hanging icicle of the first pitch of Lipton had collapsed. They also heard shouting from the area immediately after, and saw the fallen climber hanging in the rope. They notified the police, which arrived along with an ambulance crew shortly after. Three of these climbers were given a radio and some first aid equipment before they descended into the gorge. Two of them downclimbed and arrived at the scene approximately 30 minutes after the accident. The third climber rappelled down and arrived a few minutes later. Another Italian climber had also arrived at the scene shortly before that. The climber was at this time still conscious and constantly complaining about pain in his head, back, one arm and one leg.

A rescue crew started to arrive at the scene approximately an hour after the accident. Shortly after, the climber lost consciousness, and was given CPR. A Sea King helicopter was also commissioned, but was unable to help due to the difficult and narrow conditions in the gorge. Due to the massive injuries sustained, first aid was futile. Even if the climber had gotten professional care immediately after the accident, the likelihood for survival was slim to none. A doctor arriving at the scene approximately 20 minutes after CPR was started, declared the climber dead.

*Lipton before and after the accident. In addition to showing the amount of ice that fell down, one also can get an impression of how much ice that thawed away during the warm period of three days.*




*Lipton one week before the accident. The ice that collapsed is inside the red border.*

This accident was undoubtedly initiated by the large chunk of ice that fell down. It is interesting to look at the temperature history of Rjukan the previous week in order to understand how this could happen.

Gravity pulls. Both man and ice are subject to the laws of gravity. Man hangs on to the ice due to his sharp tools. Ice hangs on to the rock since it is frozen solid into the rock. Chemical bindings at the molecular level opposes the pull of gravity and prevents the ice from falling down. The week before the accident, there were huge variations in the temperature at Rjukan. For three days, the temperature was 6-7 degrees Celsius during daytime. The temperature then dropped again during the weekend. Most of the ice will then remain at a relatively high temperature, making it soft and easy to climb, while the stability of the ice may be compromised.

Warm temperatures of around 6-7 degrees for the three days prior to the weekend will have induced weakness in the hanging ice that was under high levels of tension due to having no base of support. One cannot say for certain that the ice fell down because it was climbed upon. Sometimes the ice comes down by itself as well due to the pull of gravity.

The accident serves as a sad reminder that ice can be unstable, and that we always need to evaluate the conditions carefully before starting a climb.




*Lipton just after the accident. The red dot indicates the placement of the ice screw that stopped the fall. Photo by Robert Goodman*



# Addendum

One week after the fatal accident, and after the publishing of the original report from the accident, two climbers made a rappel down Lipton in search for answers to what could have caused the accident. Their findings shed additional light on the course of events that took place during the accident. Their findings, and some conclusions based upon this is presented in this addendum.

They found the ice screw that stopped the fall still in place where the climber originally put it. A dyneema quickdraw (orange) was clipped into the screw, and this was extended by an open nylon sling (blue). This is usually done here to prevent the rope from jamming and getting stuck in the rock. While the screw and the carabiners are undamaged, the nylon sling shows extensive damage. Upon closer examination, it turns out that the nylon sling has almost ripped apart in the upper end. Only 25% of the weaving is left where the sling was damaged.



*The screw that arrested the fall. Untouched after the accident. Note the ripping in the upper end of the blue sling.  
Photo by Martin Skaar Olsund*





*Enormous forces has been at work during the fall and almost completely ripped the nylon sling.  
Photo by Martin Skaar Oslund*

While there was no clear conclusion in the initial report of whether the falling ice was attached to the climber's last ice screw or not, the new information gives overwhelming evidence in support of a conclusion that the screw was indeed attached to the large chunk of ice that fell down. There is no likely scenario in which the sling could have sustained this kind of damage from friction against rock or falling ice given its placement. The only likely explanation left is that the forces in play has been enormous, and that the sling has been exposed to forces of approximately 22 kN (weight of 2200 kg). The massive amount of ice that fell down must have exerted a strong pull in the rope in order to create this kind of force. The equipment is not built to handle the forces of a mass of several hundred kilos in a lead fall.

Given the scenario with a chunk of falling ice weighing several hundred kilos attached to the rope via an ice screw and a quickdraw, the climber will stand no chance. The climber will be pulled off the ice with enormous forces. Since he is attached to the end of the rope which pulls him down in addition to gravity, his acceleration will be larger than that of the falling ice. He will come underneath the ice and be smashed by it as the ice hits the climber's end of the rope.

We hope the report and the addendum can help us to understand better what happened in the accident, that we can all learn a bit and hopefully avoid similar accidents in the future.

## Take care and stay safe!